



[Back to INDEX](#)

SERVICE UPDATE

To: All Service Facilities and Distributors

Subject: New Style Oil Pick Up

January 10, 2007


Models Affected: 2200, 2500, 2600, 2750, 2775, 2900, 3050, PP255, PP295, PP310, PP315, PP4620AV, PP4620AVHD, PP4620AVL

A new one piece oil pickup assembly has been introduced for the above models. The new part number is **545-047801**. This new part replaces part 530-037057.

The improved part will eliminate issues seen with these saws involving leakage, sporadic oiling and no oiling situations. Normal warranty will apply.

When replacing the pickup assembly, the oil seal 530-019174 will not be re-used and can be discarded.

Below is a diagram of the new one piece pickup assembly.



[Back to INDEX](#)